

50 YEARS OF IN-GROUND CORROSION PREVENTION



Water main wrapped in Denso™ Tape more than 50 years ago.

PROJECT DATA

Location	Kings Park, WA
Client	Water Corporation
Products	Denso™ Tape
Date	More than 50 years ago
Ref No	B044

PROJECT DETAILS

A redundant water main wrapped in Denso™ Tape has recently been discovered in Kings Park, situated on 400 hectares overlooking the Swan River and Perth CBD.

The Denso™ Tape removed from the pipe has a cloth carrier as opposed to the synthetic carrier used since 1969 in Australia, indicating that this particular pipe wrap has provided over 50 years of in-ground service with the pipe still showing no signs of corrosion on its surface. Denso's Petrolatum Tapes have a proven track record providing above-, below ground and underwater protection for pipelines and other infrastructure dating back more than 80 years. Denso's petrolatum tape wrap systems can easily be applied by hand to most surfaces in a wide variety of low to high temperature environments.

DATE PUBLISHED: JUNE 2020